

Inspection Photos
Location Name: Treleaven-Government 7
API: 05-081-05243



Photo 1. Overview of location taken at entrance facing north.



Photo 2. Sediment migration on and across lease road.

Inspection Photos
Location Name: Treleaven-Government 7
API: 05-081-05243



Photo 3. Broken wattle, sediment migration.



Photo 4. Wattle not preventing sediment migration.

Inspection Photos
Location Name: Treleaven-Government 7
API: 05-081-05243



Photo 5. Sediment migration across lease road.



Photo 6. Sediment migrating off lease road.