

Chris Mccrickard  
URSA OPERATING COMPANY LLC  
1600 BROADWAY ST STE 2600  
Denver, CO 80202

Dear Mr. Mccrickard,

URSA OPERATING COMPANY LLC is receiving this letter because, based on COGCC records, the COGCC has reason to believe that in addition to the Well on the Warning Letter the Well provided below present one or more compliance issues. The Well provided below must be brought into compliance or be compliant by the date provided on the Warning Letter. Please do not hesitate to contact me with any questions regarding this compliance issue, or if this Well is incorrectly reported as non-compliant.

1. CSF 21C-18-07-91-API#045-12619

Thank you,

**Ryan Daigle**

Engineering Technician



P 303.894.2100 x5168 | F 303.894.2105

1120 Lincoln Street, Suite 801, Denver, CO 80203

[ryan.daigle@state.co.us](mailto:ryan.daigle@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)