

GOLDEN EAGLE MINE GE -72-93 API# 05-071-06456– TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 30, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102766



PHOTO 1: FACING SOUTHWEST TOWARD THE RECLAIMED ACCESS ROAD.

GOLDEN EAGLE MINE GE -72-93 API# 05-071-06456– TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 30, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102766



PHOTO 2:THE LOCATION AND ACCESS ROAD RECLAMATION WERE RESEEDED WITH HYDRO-MULCH USING AN APPROVED HILL RANCH SEED MIX FOR SOIL STABILIZATION AND TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

GOLDEN EAGLE MINE GE -72-93 API# 05-071-06456– TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 30, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102766



PHOTO 3: THE LOCATION AND ACCESS ROAD RECLAMATION WERE RESEEDING WITH HYDRO-MULCH USING AN APPROVED HILL RANCH SEED MIX FOR SOIL STABILIZATION AND TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

GOLDEN EAGLE MINE GE -72-93 API# 05-071-06456– TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 30, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102766




PHOTO 4: THE LOCATION AND ACCESS ROAD RECLAMATION WERE RESEEDING WITH HYDRO-MULCH USING AN APPROVED HILL RANCH SEED MIX FOR SOIL STABILIZATION AND TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

GOLDEN EAGLE MINE GE -72-93 API# 05-071-06456– TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 30, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102766



PHOTO 5: THE SIGN HAS BEEN REMOVED FROM LOCATION.

GOLDEN EAGLE MINE GE -72-93 API# 05-071-06456– TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: APRIL 30, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102766



PHOTO 6: THE OLD GROUNDING ROD HAS BEEN REMOVED FROM LOCATION.