

Inspection Photo
Leverich Federal 31-16D
API# 045-15723
Inspection # 689301040



Location photo # 1



Location photo #2 slope erosion near separators, looking south

Inspection Photo
Leverich Federal 31-16D
API# 045-15723
Inspection # 689301040



Location photo # 3 slope erosion near separators, looking south

Location photo # 4 slope erosion near separators, looking south

Inspection Photo
Leverich Federal 31-16D
API# 045-15723
Inspection # 689301040



Location photo # 5 slope erosion near separators, looking south



Location photo # 6 slope erosion near separators, looking south

Inspection Photo
Leverich Federal 31-16D
API# 045-15723
Inspection # 689301040



**Location photo # 7 slope erosion near
separators, looking south**