

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401631283
Date Received:
05/07/2018

FIR RESOLUTION FORM

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96340
Name of Operator: WIEPKING-FULLERTON ENERGY LLC
Address: 96 GLENMOOR LN
City: ENGLEWOOD State: CO Zip: 80113
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Linda Boone	(720) 941-0791	haldeoil@hotmail.com therian1@cox.net LDBoonePar@aol.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682503289
Inspection Date: 04/30/2018 FIR Submit Date: 05/01/2018 FIR Status:

Inspected Operator Information:

Company Name: CASCADE PETROLEUM LLC Company Number: 10414
Address: P O BOX 3316
City: DENVER State: CO Zip: 80155

LOCATION - Location ID: 436744

Location Name: CRAIG Number: 9S-55W-19-41 County:
Qtrqtr: SWS Sec: 19 Twp: 9S Range: 55W Meridian: 6
Latitude: 39.245710 Longitude: -103.600720

FACILITY - API Number: 05-073-00 Facility ID: 436744

Facility Name: CRAIG Number: 9S-55W-19-41
Qtrqtr: SWS Sec: 19 Twp: 9S Range: 55W Meridian: 6
Latitude: 39.245710 Longitude: -103.600720

CORRECTIVE ACTIIONS:

1 CA# 116184

Corrective Action:

Date: 03/31/2018

Perform reclamation in accordance to COGCC 1000 series rules on the access road, including by not limited to, removing gravel, compaction alleviation, regrading/recontouring and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be complete no later than 3/31/2018.

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator Comment: On March 26, 2018 the access road was de-compacted where vehicle traffic caused compaction on the 2-track access road. Decompaction was not conducted in the middle of the 2-track access road due to established native vegetation. The decision was made that de-compacting the areas between the 2-track would cause damage to the established vegetation and would not add any benefits to vegetation growth as the vegetation was already present when reclamation activities began. The access road was also seeded and stabilized on March 28, 2018. Wiepking-Fullerton does not believe that it is our responsibility to reclaim the ~1,200 feet of access road south of the east to west ranch road to the previously existing Harris 9-13 well pad (API#: 05-073-06118) operated by Sohio Petroleum Company. The access road previously existed prior to Cascade (previous owner of the access road in question) installing the road and well pad as Sohio Petroleum was responsible for reclamation activities for the north ~1,200 feet of access road. The COGCC approved final reclamation status for the Harris 9-13 well pad and access road on November 6, 1986, therefore Wiepking-Fullerton recognizes that the north ~1,200 feet of the access road was pre-existing and, therefore, Wiepking-Fullerton should not be held responsible for reclamation activities on the north ~1,200 feet of access road. Wiepking-Fullerton will continue to monitor and manage the reclaimed portion of the access road and well pad until the site passes final reclamation status per COGCC Rule 1004.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor:

Corrective actions and corrective action date remains applicable. The road leading to the south from the east/west road was developed, existed and consistently used for Oil and gas access. WFE is the last operator to use the access road for oil and gas activities. Additionally the road appears to have been re-disturbed within the time frame WFE used the access road for oil and gas access.

Documentation shows compaction concerns remain evident on the access road and reclamation activities (including by not limited to compaction alleviation, removal of road base/gravel, re-contouring and re-grading) have not been performed in accordance to COGCC 1000 series reclamation standards and requirements. In addition, photos from inspection #682503289 shows that the inadequate reclamation work conducted by operator appears to have removed any vegetation that did exist on the center of the access road.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Linda Boone

Signed: _____

Title: Agent

Date: 5/7/2018 12:08:44 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401631283	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files