

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401623162
Date Received:
04/27/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () Fax: ()
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Fitzgerald, Edie</u>	<u>719-845-2108</u>	<u>ediefitzgerald@tcenergy.us</u>
<u>Amato, Joseph</u>	<u>719-845-2110</u>	<u>josephamato@tcenergy.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102757
Inspection Date: 03/07/2018 FIR Submit Date: 03/20/2018 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 307410

Location Name: GOLDEN EAGLE MINE-633S67W Number: 21SESW County: LAS ANIMAS
Qtrqr: SESW Sec: 21 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.153979 Longitude: -104.896101

FACILITY - API Number: 05-071-00 Facility ID: 217626

Facility Name: GOLDEN EAGLE MINE Number: NW-3-6-95
Qtrqr: SESW Sec: 21 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.153979 Longitude: -104.896101

CORRECTIVE ACTIONS:

1 ☒ CA# 115049

Corrective Action: Perform Final Reclamation per COGCC 1004 Rules, including but not limited to recontouring, replacement of topsoil, and seeding of site. Install and maintain appropriate BMPs to stabilize location until uniform vegetation establishes across all disturbance areas. All reclamation activities to be complete by May 15, 2018.

Date: 05/15/2018

Response: CA COMPLETED Date of Completion: 04/26/2018

Recontoured the well pad to match the surrounding terrain. Replaced the top soil during reclamation activities. Grading techniques were installed on the contour to promote ground infiltration and to prepare the soil for

Operator seeding. A dirt berm was used as perimeter sediment control. All disturbed soils were stablized by hydro seeding
Comment: with an approved Hill Ranch seed mix.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The corrective actions have been addressed regarding COGCC FIR Doc # 680102757

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 4/27/2018 1:02:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

401623162	FIR RESOLUTION SUBMITTED
401623177	Well pad reclamation photos

Total Attach: 2 Files