

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401635741  
Date Received:  
05/10/2018

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) Fax: ( )  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Fitzgerald, Edie</u>	<u>719-845-2108</u>	<u>ediefitzgerald@tcenergy.us</u>
<u>Amato, Joe</u>	<u>719-845-2110</u>	<u>josephamato@tcenergy.us</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 680102754  
Inspection Date: 03/07/2018 FIR Submit Date: 03/20/2018 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 307409

Location Name: GOLDEN EAGLE MINE-633S67W Number: 21NWSE County: LAS ANIMAS  
Qtrqtr: NWSE Sec: 21 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.154448 Longitude: -104.891449

### FACILITY - API Number: 05-071-00 Facility ID: 217625

Facility Name: GOLDEN EAGLE MINE Number: 3N-2-95  
Qtrqtr: NWSE Sec: 21 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.154448 Longitude: -104.891449

### CORRECTIVE ACTIONS:

1 ☒ CA# 115034

Corrective Action: Perform Final Reclamation per COGCC 1004 Rules including re-contouring, seeding of site and reclamation of access road. Install appropriate BMPs to stabilize location until vegetation establishes. All Reclamation Activities to be complete by May 15, 2018.

Date: 05/15/2018

Response: CA COMPLETED Date of Completion: 05/09/2018

Operator Comment: Reclamation of the well pad and access road are complete. The top soil was utilized during reclamation activities. Grading techniques were installed on the contour. All disturbed soils were stabilized by hydro seeding with an approved Hill Ranch seed mix. The silt fence, stakes, location sign and top soil sign were removed from location.

The erosion issues were all corrected during the reclamation. (3) water bars were installed on the access road and (1) on the well pad. See attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: Sr. Environmental Tech.

Date: 5/10/2018 9:32:28 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401635741	FIR RESOLUTION SUBMITTED
401635778	Reclamation photos

Total Attach: 2 Files