

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401643267

Date Received:

05/17/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|------------------------|-------|------------------------|
| Beebe, Sabre | | sabre.beebe@bp.com |
| Inspections, All | | SanJuanCOGCC@bp.com |
| St John, William (Cal) | | cal.stjohn@state.co.us |

COGCC INSPECTION SUMMARY:

FIR Document Number: 685200425
Inspection Date: 03/26/2018 FIR Submit Date: 03/27/2018 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326067

Location Name: MW JOHNSON G A-M34N8W Number: 16NWNW County: LA PLATA
Qtrqr: NWN Sec: 16 Twp: 34N Range: 8W Meridian: M
W
Latitude: 37.195509 Longitude: -107.727750

FACILITY - API Number: 05-067-00 Facility ID: 215812

Facility Name: MW JOHNSON A Number: 1
Qtrqr: NWN Sec: 16 Twp: 34N Range: 8W Meridian: M
W
Latitude: 37.195509 Longitude: -107.727750

CORRECTIVE ACTIIONS:

1 CA# 115261

Corrective Action: use or remove parts and equipment per Rule 603.f Date: 04/27/2018
Response: CA COMPLETED Date of Completion: 05/25/2018

All operator debris removed from location and properly disposed of. See attached photos

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 115262

Corrective Action: Stop release as soon as possible and no later than corrective action date, take necessary steps in engine repair or muffler re-configuration to prevent recurrence per Rules 906 & 907 (see stormwater section for CA regarding removal of impacted material)

Date: 04/06/2018

Response: CA COMPLETED

Date of Completion: 04/06/2018

Operator
Comment:

Containment box installed on muffler to prevent future staining of soils from exhaust.

COGCC Decision:

COGCC
Representative:

3 CA# 115263

Corrective Action: Clean up (do not cover) impacted material on east side of pumping unit (see photos) per applicable parts of Rules 906, 907 and 1002.f

Date: 04/06/2018

Response: CA COMPLETED

Date of Completion: 04/06/2018

Operator
Comment:

All stained soils have been excavated from location and disposed of in the soil box at the BP Durango Operations Center for batch remediation at IEI in Farmington NM. Clean soils have been placed back into excavation areas to address this CA. See attached photos.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All Corrective actions have been addressed on this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 5/17/2018 7:49:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|-----------|-------------------|
| 401643294 | CA closure photos |
|-----------|-------------------|

Total Attach: 1 Files