

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401646674

Date Received:

05/21/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602614

Inspection Date: 04/12/2018

FIR Submit Date: 04/27/2018

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326481

Location Name: ARGENTA 34-10-M34N10W Number: 32NENW County: LA PLATA

Qtrqr: NENW Sec: 32 Twp: 34N Range: 10W Meridian: M

Latitude: 37.152180 Longitude: -107.960410

FACILITY - API Number: 05-067-00 Facility ID: 216565

Facility Name: ARGENTA 34-10 Number: 32-1

Qtrqr: NENW Sec: 32 Twp: 34N Range: 10W Meridian: M

Latitude: 37.152180 Longitude: -107.960410

CORRECTIVE ACTIONS:

1 CA# 116109

Corrective Action: Remove trash and debris.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/15/2018

Operator Comment: Trash and debris removed. See attached photos.

COGCC Decision: _____

COGCC
Representative:

2 CA# 116110

Corrective Action: Area with bare soils in the eastern fill slope needs revegetation. If current conditions are not favorable for seeding, erosion control materials such as erosion control blanket or flexterra, can be installed until seeding timing is favorable, but no later than November 1, 2018.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/15/2018

Operator Comment: Stormwater management controls have been established to stabilize erosion of fill slope bare soil areas in eastern area until there is a more favorable time for seeding the area. See attached photos.

COGCC Decision:

COGCC
Representative:

3 CA# 116111

Corrective Action: Maintain wattles in the northeastern project area and stabilize bare soils in the eastern project area, as described above.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/15/2018

Operator Comment: Wattles on the northeast edge of project has been cleaned and maintained to stabilize erosion. See attached photos.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: Operations Reg Technician

Date: 5/21/2018 6:13:51 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401646675	ARGENTA 34-10 32-1 CORRECTIVE PHOTOS
-----------	--------------------------------------

Total Attach: 1 Files