

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2018

Submitted Date:

05/22/2018

Document Number:

689801110**FIELD INSPECTION FORM**Loc ID 324591 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kauffman, KP		cogcc@kpk.com	<a href="#">All Inspections</a>
		dnr_cogccenforcement@state.co.us	
		dnr_cogccengineering@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212077	WELL	IJ	12/28/1984	DSPW	057-05129	DWINELL 1	SI

**General Comment:**[UIC 5 year MIT.](#)

**Inspected Facilities**Facility ID: 212077 Type: WELL API Number: 057-05129 Status: IJ Insp. Status: SI**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: DK-LK

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 06/18/2013

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: 5 Year Tbg psi: 750 Csg psi: 1850 BH psi: 0Insp. Status: Fail Leak Type: \_\_\_\_\_Comment: Packer 142 feet away from top perforated interval. Test witnessed in field but not passed due to lack of compliance with Rule 326.a.Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan. Date: 06/05/2018**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801112	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470793">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470793</a>