

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/19/2018

Submitted Date:

05/22/2018

Document Number:

689100157**FIELD INSPECTION FORM**Loc ID 335537 Inspector Name: LUJAN, CARLOS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne		dknudson@ursaresources.com	Environmental Manager
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
Holtz, Darin		darin.holtz@state.co.us	Inspector, NW Region
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335537	LOCATION	AC			-	VALLEY FARMS-66S92W 15SWNW	EI

General Comment:

Environmental inspection conducted in response to Inspection doc #689300912 that included "Actions Required". As part of the required actions URSA contacted COGCC environmental staff. On site with Dwayne Knudson, URSA environmental manager. Cleanup operations of secondary containment staining were in process and were planned for other sites.

Inspected FacilitiesFacility ID: 335537 Type: LOCATION API Number: - Status: AC Insp. Status: EI**COGCC Comments**

Comment	User	Date
No follow-up environmental inspection required. Comply with Inspector Required Actions. Inspector group may conduct follow-up inspections	lujanc	05/22/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689100158	Staining in secondary containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4470789