

On 5/23/2018 COGCC Environmental staff inspected the spill path of spill number 438684. Chevron has requested closure of the spill. No visual impact was detected during the inspection. Chevron should continue to monitor vegetative growth and Reclamation of the spill site per rule 909.b.(6). On the pad and just adjacent to the pad (to the Southeast) there were open excavations exposing the pipe. The excavation appeared to be done with water knife, there was no overburden stored on pad.

Inspection 685100478

















05.23.2018 12:24







Chevron U.S.A., Inc.
A.C. McLAUGHLIN 22
API #05-103-01055
640' FSL & 1995' FWL USE SW1 SECTION 14, T2M R003M 60 FM
LAT 40.13762092 / LONG -108.9259071
IN CASE OF EMERGENCY CALL 9701675-3700

05.23.2018 12:23

