

ABC FIRE & SAFETY

**1602 South Broadway
Cortez, Colorado 81321
(970) 565-6100**

Report on Gas Detection for State of Colorado Oil and Gas 5/11/2018


The gas readings taken on location near Breen, CO showed no evidence of Hydrogen Sulfide (H₂S). The only reading received was **0 – 49% LEL** (methane) fluctuating between the two at different times. In attendance were Steve Labowskie and Jim Hughes.

**Monitor Peaks H₂S 0 ppm
CO 0 ppm
CO₂ 0 ppm
LEL 49 %
O₂ 20.9%**

Monitor Used

MSA Altair 5X
Ser. # 00006333
Calibrated 5/10/18

Gas Monitoring performed by Travis Mikkelson


5/11/2018