

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401631468
Date Received:
05/08/2018

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 34725
Name of Operator: GOSNEY & SONS INC
Address: P O BOX 367
City: BAYFIELD State: CO Zip: 81122
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Barnett, Matt		mattb@gosneyco.com
Leonard, Mike		mike.leonard@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 685304330
Inspection Date: 02/08/2018 FIR Submit Date: 02/12/2018 FIR Status:

Inspected Operator Information:

Company Name: GOSNEY & SONS INC Company Number: 34725
Address: P O BOX 367
City: BAYFIELD State: CO Zip: 81122

LOCATION - Location ID: 325536

Location Name: GOSNEY-M34N7W Number: 14NWNW County: LA PLATA
Qtrqr: NWN Sec: 14 Twp: 34N Range: 7W Meridian: M
W
Latitude: 37.195140 Longitude: -107.583300

FACILITY - API Number: 05-067-00 Facility ID: 214965

Facility Name: GOSNEY Number: 1
Qtrqr: NWN Sec: 14 Twp: 34N Range: 7W Meridian: M
W
Latitude: 37.195140 Longitude: -107.583300

CORRECTIVE ACTIIONS:

1 CA# 114405

Corrective Action: Comply with Rule 603.f. Date: 03/15/2018

Response: CA COMPLETED Date of Completion: 05/07/2018

Operator Comment: The first two unused riser/flowlines (photos 2 and 3 in Form INSP) are a steel supply gas line from the separator to the wellhead (on-location). The wellhead riser has been repaired, and the upstream riser is isolated from the pressure source by lock-out tag-out. The third unused riser (photo 4) has been removed. The fourth riser (photo 5) is located downstream of a domestic tap. We are working with the landowner on several changes to their tap

gas system. In connection therewith, the fourth riser will be removed as soon as weather conditions allow for temporary tap gas shut-in and safe locating and excavating, anticipated no later than April 30. In the meanwhile the valve on the riser is locked out and tagged out. May 7, 2018 update: Fourth riser has been removed. All CA's completed.

COGCC Decision: Approved

COGCC Representative: Follow up inspection completed.

2 CA# 114406

Corrective Action: Remove abandoned sections of flowline to comply with Rule 603.f. Date: 05/14/2018

Response: CA COMPLETED Date of Completion: 05/07/2018

Operator Comment: Abandoned sections of flowline, which were subsequently unearthed by landowner's gravel mining excavation, have been removed.

COGCC Decision: Approved

COGCC Representative: Follow up inspection completed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Barnett Signed: _____

Title: Gen Mgr Date: 5/8/2018 2:58:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401631468	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files