


WELLBORE DIAGRAM
EXTRACTION OIL & GAS
Sanchez #33-10R
NWSE 10 T5N R65W
Weld County
05-123-23188



- Bradenhead test required prior to P&A, gas
- ☒ sample if surface casing > 25 psi, results to Denver within 10 days
- ☐ Gyro required
- ☐ CBL required

Special Instructions: Perform low pressure test on all CIBP.
*Tag and pressure test existing CIBP