

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2018

Submitted Date:

07/05/2018

Document Number:

688800191**FIELD INSPECTION FORM**Loc ID 335966 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Wilbourn, Don		dwilbourn@bry.com	
Johnson, Derek	970-285-2200	djohnson@bry.com	<a href="#">Dist. Superintendent</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443338	LAND APPLICATION SITE	AC	09/25/2015		-	Chevron O06 696 443338	EI

**General Comment:**

On May 17, 2018 COGCC West Environmental Supervisor Alex Fischer and SW EPS Jim Hughes conducted an environmental field inspection of the Berry Chevron O06 696 Land Application Site, Facility ID #443338. Berry representatives Derek Johnson and Don Wilbourn were present during this field inspection. For the most recent field inspection report for this facility, please refer to document #689100006.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on location sign.

Corrective Action:  Date:

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Continue to remove liner pieces as they become exposed in land farmed material.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Land Treatment	Adequate		
Comment				
Corrective Action				Date:

**Spill/Remediation:**

Comment: [Please refer to REM #10050 for more information regarding the land farm project on this location.](#)

Corrective Action:  Date:

Emission Control Burner (ECB): Comment: Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
				Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On May 17, 2018 COGCC West Environmental Supervisor Alex Fischer and SW EPS Jim Hughes conducted an environmental field inspection of the Berry Chevron O06 696 Land Application Site, Facility ID #443338. Berry representatives Derek Johnson and Don Wilbourn were present during this field inspection. For the most recent field inspection report for this facility, please refer to document #689100006. Land farmed material had recently been tilled at the time of this inspection. Continue to remove liner pieces as they become exposed.	hughesj	07/05/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800192	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515167">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4515167</a>