

244 BURTARD LN

1835

To Urea Date 6-27-18
Address Hings A Purchase Order No. _____
Location Dave

Description of Work	Hours
Plug and Abandon Conductors	
ft+ A tie A-1 And A-3	
Cut Conductors to 4 feet below ground grade	
Fill with gravel and concrete	
weld Cap on conductor	
A-1 AP1 # 05-045-13763	
A-3 AP1 # 05-045-12336	

No.	Equipment & Material	Hours	Rate	Amount	Labor	Hours	Rate	Amount
	Pickup	1			Foreman	2		
	Table	1			Labor			
	JD 50 mini ex	4			Labor			
	welder (JD)	4			Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Labor			
					Total labor			
					Total Equip.			

Total Equipment _____ Total _____

Purchaser *Justin Hargis* Date 7-5-18 By _____