

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/12/2018

Submitted Date:

07/17/2018

Document Number:

690300298**FIELD INSPECTION FORM**

Loc ID 322357	Inspector Name: Spencer, Stan	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 2 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	
Arauza, Steven		steven.arauza@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Byers, Jim	970 -876 -9056	jbyers@blm.gov	NRS

General Comment:

Pre-closure inspection of two pits on locations. Only one pit (#111764 is listed) with no information in Scout Card. REM#11310 includes investigation and closure of both pits. One pit located at SE corner of pad is ~15'x15'x5'deep. Pit is netted and appears to have had soil samples recently collected. Pit is dry with no odor or staining observed. Second pit is on the west side of the pad to the south of the separator. Pit is ~15'x15'x3ft deep. Pit is netted and dry with no staining or odor observed. Both pits have rusted steel discharge pipes entering with no apparent ongoing inflow to pits.

Complete site investigation per REM 11310. If sample results are Table 910-1 compliant, submit Supplemental F-27 "request for closure". If not, submit Supplemental F-27 with remediation plan to bring soils into Table 910-1 compliance. If remediation includes either in-situ or onsite treatment, surface owner (BLM) permission must be obtained prior to implementation. Notify COGCC a minimum of 72 hrs prior to remediation activity.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
690300299	Pit insp photos 7-12-18	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525562