

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2018

Submitted Date:

08/03/2018

Document Number:

682503696**FIELD INSPECTION FORM**
 Loc ID 311709 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 65550Name of Operator: OILFIELD SALVAGE & SERVICE COAddress: 5911 S MIDDLEFIELD RDCity: LITTLETON State: CO Zip: 80123**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		oilfieldsalvage@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200049	WELL	PA	08/17/1995	DSPW	001-05051	NOONEN RANCH 10	RI

General Comment:

This is a follow-up, final reclamation and stormwater inspection to doc. #682501125, #682501478, doc. #675103751 and #682502970.
Any corrective actions from previous inspections that have not been addressed area still applicable.

Inspected Facilities									
Facility ID:	200049	Type:	WELL	API Number:	001-05051	Status:	PA	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control **Fail** _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [SEE "COGCC COMMENTS" FOR COMMENTS REGARDING RECLAMATION](#)

Corrective Action: _____ Date **12/18/2017**

Perform reclamation in accordance to COGCC 1000 series rules and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Recommend operator assess soil agronomic and possible compaction concerns. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Overall Final Reclamation

Fail

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					
Waddles	Fail					

Comment: [SEE "COGCC COMMENTS" REGARDING STORMWATER](#)

Corrective Action: Properly select, install and maintain required site specific stormwater and erosion controls in accordance with 1002.f and good engineering practices.

Date: 09/09/2016

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>RECLAMATION COMMENT</p> <p>Previous inspections required operator to perform reclamation, including establishing vegetation, stabilizing the site and ensuring erosion controls are implemented to stabilize the seeded soil. Previous reclamation activities appear to have been conducted and reclamation was placed "in process" in inspection #682502970, however concerns were identified and that additional reclamation will likely be required as no controls were implemented to stabilize the seeded soil, and what BMPs were installed were not been installed in accordance to good engineering practices. Operator has been called and notified multiple times after the previous inspections that the location remains at risk. It has been determined that the reclamation has failed; erosion degradation has been allowed to continue (see stormwater) and will require repair, no desirable perennial vegetative germination evident. A corrective action date of 12/18/2017 will be used as this was the most recent inspection date; See attached Photos Inspector will contact operator again after submission of this inspection.</p>	trujilloam	08/03/2018

STORMWATER COMMENTS

trujilloam

08/03/2018

Previous inspections required operator to perform stormwater management and to properly select and install site specific stormwater and sediment control BMPs. Inspections also required (under final reclamation) operator to ensure erosion controls are implemented to stabilize the seeded soil.

Inspector visited the location in October 3rd, 2017 when work was being conducted on the site. It was noted that the area appeared to have been seeded and straw wattle ponding BMPs were being used as a control. However, it was also noted that no additional controls were implemented to stabilize the seeded soil per corrective action requirements under reclamation, and the straw wattle BMPs were not properly installed (trenched) in accordance to good engineering practice. Inspector contacted the operator (Mr. Unruh) immediately after making these observations and informed him that the seeded soil is at risk to both wind and stormwater erosion, and that BMPs will need to be correctly installed.

Upon follow-up inspection on 12/18/2017, it was documented that no additional controls to stabilize the seeded soil have been implemented, and the straw wattle BMPs remain improperly installed and insufficient. Operator notified inspector via email on 12/26/2017 that the controls will be fixed.

Upon this inspection, it remains evident that the existing stormwater and erosion control BMPs remain improperly installed and insufficient, that no additional BMPs have been installed with good engineering practices, that stormwater has been allowed to continue to cut under the wattles and degradation has been allowed to continue on the location. See attached photo document. Original corrective action and corrective action date remains in place.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682503697	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4543527