

Operator: Sunset Hill Oil Co	Operator #:
Well Name: UPRR-SMITH 1-3	Location: Weld, CO
API: 05-123-11555	Legal: SWNW 3-6N-67W

Plugging Procedure

1. Dig down to expose surface pipe
2. Remove cap
3. Cut Surface Casing down 12' below G.L
4. Inspect Cement
5. If no cement is present pump 10 sx plug
6. Weld on new ID plate