

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401745452

Date Received:

08/27/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Recipient, Single

Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602788

Inspection Date: 06/18/2018

FIR Submit Date: 07/04/2018

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333792

Location Name: JACQUES-N33N8W Number: 27SENW County: LA PLATA

Qtrqr: SENW Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.076490 Longitude: -107.707860

FACILITY - API Number: 05-067- -00 Facility ID: 454865

Facility Name: Jaques Number: 9

Qtrqr: SENW Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.076490 Longitude: -107.707860

CORRECTIVE ACTIONS:

1 CA# 117190

Corrective Action: Stormwater controls such as silt traps and armoring are needed at culvert inlets and outlets to prevent erosion from stormwater flows along the access road. Check dams will likely be needed in roadside ditches. Stormwater controls are also needed on loose soils along roadside to prevent sediment runoff, and revegetation is needed on these soils for long term stabilization. Seeding is required by November 1, 2018 and remaining stormwater controls need to be installed by August 4, 2018.

Date: 08/04/2018

Response: CA COMPLETED

Date of Completion: 08/03/2018

Installed silt traps, armored culverts, installed check dams along road side ditches. Retrenched waddles, cleaned and reset others, repaired and cleaned out diversion ditch, cleaned repaired and reinforced rock rundown in NE corner of location.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed:

Title: Geo/Eng Tech

Date: 8/27/2018 2:27:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401745456	Remedial Report
-----------	-----------------

Total Attach: 1 Files