

# Interim Reclamation and Stormwater Inspection

August 24, 2018

Operator: NGL WATER SOLUTIONS DJ LLC- #10373

Location ID: 440281

Inspection Document #: 682403913

Weld County, CO

SWNW Section 24 T10N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: NGL /C9C & C9F  
Location ID: 440281



**Photo 1.** Photo taken from the southwestern location, facing East. Operator has not maintained the installed stormwater BMP (silt fence). Rill erosion was observed along portions of the perimeter of the location.



**Photo 2.** Photo taken from the eastern location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: NGL /C9C & C9F  
Location ID: 440281



**Photo 3.** Photo taken from the northeastern location, facing West. See comments under Photo 1.



**Photo 4.** Photo taken from the western location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: NGL /C9C & C9F  
Location ID: 440281



**Photo 5.** Photo taken from the western location, facing East. Fill slopes are not adequately stabilized to minimize erosion, transport of sediment offsite, and site degradation.



**Photo 6.** Photo taken from the western location, facing East. See comments under Photo 5.





**Photo 7.** Photo taken from the northeastern location, facing North. Does not appear the Operator has salvaged a sufficient amount of topsoil. Also, Operator has failed to properly protect the topsoil from degradation due to erosion and failed to prevent weed establishment. Appears cattle have also degraded the topsoil.



**Photo 8.** Photo taken from the northern topsoil stockpile, facing West. Photo illustrates weed establishment, erosion and degraded topsoil from cattle disturbance.