

HALLIBURTON

iCem[®] Service

HIGHLANDS NATURAL RESOURCES-EBUS

Date: Wednesday, May 16, 2018

Hagar 5-64 15-16-1BHZ

Job Date: Friday, May 04, 2018

Sincerely,
Tyler Hill

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0 Cementing Job Summary 4

 1.1 Executive Summary4

2.0 Real-Time Job Summary 7

 2.1 Job Event Log7

3.0 Attachments..... 10

 3.1 Hagar 5-64 15-16-1BHZ Surface.png10

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Hagar 5-64-15 16-1BHZ** cement **Surface** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 47.5 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Ft. Lupton

The Road to Excellence Starts with Safety

Sold To #: 378724		Ship To #: 3791456		Quote #: 0022436631		Sales Order #: 0904830012					
Customer: HIGHLANDS NATURAL RESOURCES-EBUS				Customer Rep: Mark Stoner							
Well Name: HAGAR			Well #: 5-64 15-16-1BHZ			API/UWI #: 05-005-07268-00					
Field: WILDCAT		City (SAP): AURORA		County/Parish: ARAPAHOE		State: COLORADO					
Legal Description: NE SE-15-5S-64W-2180FSL-440FEL											
Contractor: TRUE DRLG				Rig/Platform Name/Num: TRUE 33							
Job BOM: 7521 7521											
Well Type: HORIZONTAL OIL											
Sales Person: HALAMERICA\HB41307				Srvc Supervisor: Adam Covington							
Job											
Formation Name											
Formation Depth (MD)		Top		Bottom							
Form Type				BHST							
Job depth MD		2116ft		Job Depth TVD							
Water Depth				Wk Ht Above Floor							
Perforation Depth (MD)		From		To							
Well Data											
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft	
Open Hole Section			13.5				0	2116		0	
Casing		9.625	8.921	36	LTC	J-55	0	2158		0	
Tools and Accessories											
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make		
Guide Shoe	9.625			2158		Top Plug	9.625	1			
Float Shoe	9.625					Bottom Plug	9.625		HES		
Float Collar	9.625					SSR plug set	9.625		HES		
Insert Float	9.625					Plug Container	9.625		HES		
Stage Tool	9.625					Centralizers	9.625	25	HES		
Fluid Data											
Stage/Plug #: 1											
Fluid #	Stage Type	Fluid Name			Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	Fresh Water Spacer	Fresh Water Spacer			20	bbl	8.33			2	

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	SwiftCem	SWIFTCEN (TM) SYSTEM	330	sack	12	2.53		8	14.65
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	SwiftCem	SWIFTCEN (TM) SYSTEM	440	sack	13.5	1.76		8	9.02
9.02 Gal		FRESH WATER							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
4	Displacement	Displacement	162.5	bbl	8.33			10	
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
5	HALCEM	HALCEM (TM) SYSTEM	0	sack	15.8	1.09		1	4.7
5.15 Gal		FRESH WATER							
Cement Left In Pipe		Amount	40 ft			Reason		Shoe Joint	
Comment 47.5 bbls back to surface. Estimated top of tail is 568.96 ft. Checked floats, got 2 bbls back to the truck. Floats held.									

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	PS Pump Press (psi)	DH Density (ppg)	Comb Pump Rate (bbl/min)	Comments
Event	1	Call Out	Call Out	5/4/2018	00:30:00	USER				CALLED OUT BY SERVICE COORDINATOR FOR O/L AT 0700
Event	2	Pre-Convoy Safety Meeting	Depart Shop for Location	5/4/2018	04:20:00	USER				HELD MEETING WITH ALL PERSONNEL IN CONVOY TO DISCUSS DIRECTIONS AND HAZARDS ASSOCIATED WITH DRIVING, ALL FIT TO DRIVE.
Event	3	Depart Shop for Location	Depart Shop for Location	5/4/2018	04:30:00	USER				JOURNEY MANAGEMENT PRIOR TO DEPARTURE
Event	4	Arrive At Loc	Arrive At Loc	5/4/2018	06:00:00	USER				UPON ARRIVAL MET WITH COMPANY MAN TO DISCUSS JOB DETAILS AND CALCULATIONS, PERFORMED HAZARD HUNT AND SITE ASSESSMENT.
Event	5	Safety Meeting - Pre Rig-Up	Safety Meeting - Pre Rig-Up	5/4/2018	06:45:00	USER				DISCUSSED RIGGING UP HAZARDS AND PROCEDURE ACCORDING TO HMS.
Event	6	Safety Meeting - Pre Job	Safety Meeting - Pre Job	5/4/2018	09:15:00	USER	0.00	8.39	0.00	HELD SAFETY MEETING WITH ALL JOB ASSOCIATED PERSONNEL TO DISCUSS JOB PROCEDURE, HAZARDS AND STOP WORK AUTHORITY. Water test-PH-6, Chlor-0, Temp-65. Cement temp-70.
Event	7	Start Job	Start Job	5/4/2018	09:38:46	COM4	0.00	8.47	0.00	FILLED LINES WITH 3 BBLS OF FRESH WATER. 2 BPM

										30 PSI.
Event	8	Test Lines	Test Lines	5/4/2018	09:42:10	COM4	14.00	8.38	0.00	TESTED LINES TO 3000 PSI. AFTER A 500 PSI KICKOUT TEST AND A 5TH GEAR STALL. HAD TO BUMP AND HELD FOR A MINUTE.
Event	9	Pump Spacer 1	Pump Spacer 1	5/4/2018	09:47:55	COM4	20.00	8.40	1.80	PUMPED 10 BBLS OF DYED WATER SPACER. AT 2 BPM 30 PSI.
Event	10	Pump Spacer 2	Pump Spacer 2	5/4/2018	09:53:22	COM4	35.00	8.37	1.90	PUMPED 10 BBLS OF FRESH WATER SPACER AT 2 BPM 35 PSI.
Event	11	Pump Lead Cement	Pump Lead Cement	5/4/2018	09:57:41	COM4	52.00	8.36	2.60	PUMPED 149 BBLS (330 SKS) OF 12#, 2.53y, 14.65 OF SWIFT CEM. 8 BPM 200 PSI.
Event	12	Check Weight	Check Weight	5/4/2018	10:00:19	COM4	174.00	11.97	6.20	USED PRESSURIZED MUD SCALES TO WEIGH UP CEMENT. CEMENT WEIGHED UP AT 12#
Event	13	Pump Tail Cement	Pump Tail Cement	5/4/2018	10:18:48	COM4	326.00	13.09	8.00	PUMPED 138 BBLS (440 SKS) OF 13.5#, 1.76y, 9.02wr. AT 8 BPM 230 PSI.
Event	14	Check Weight	Check Weight	5/4/2018	10:19:55	COM4	266.00	13.37	6.90	USED PRESSURIZED MUD SCALES TO WEIGH UP CEMENT. CEMENT WEIGHED UP AT 13.5#
Event	15	Drop Top Plug	Drop Top Plug	5/4/2018	10:45:13	COM4	22.00	14.01	0.00	DROPPED NON HALLIBURTON 9 5/8" TOP PLUG. CO. MAN WITNESSED, ADAM COVINGTON DROPPED PLUG.
Event	16	Pump Displacement	Pump Displacement	5/4/2018	10:45:27	COM4	22.00	14.00	0.00	PUMPED 162.5 BBLS OF BIOCIDES DISPLACEMENT (PROVIDED BY CO. MAN)

										HAD TO SHUT DOWN AT 95 BBLS AWAY WHEN WE GOT SPACER SO RIG COULD SWAP LINES.
Event	17	Bump Plug	Bump Plug	5/4/2018	11:19:40	COM4	1240.00	7.54	0.00	BUMPED NON HALLIBURTON 9 5/8" TOP PLUG. FCP WAS 609 PSI. TOOK TO 1145 PSI. HELD FOR 10 MINUTE CASING TEST, BUT A BLEED OFF IN THE CELLER WAS LEAKING. RIG CREW TIGHTENED IT.
Event	18	Other	Other	5/4/2018	11:38:32	COM4	1326.00	7.58	0.00	BUMPED PRESSURE UP AFTER BLEED OFF WAS TIGHTENED. AND HELD FOR 10 MORE MINUTES AS PER CO. MAN. PRESSURE HELD.
Event	19	Check Floats	Check Floats	5/4/2018	11:49:26	USER	1306.00	7.61	0.00	BLD PRESSURE BACK. GOT 2 BBLS OF WATER BACK TO THE TRUCK. FLOATS HELD.
Event	20	End Job	End Job	5/4/2018	11:51:12	COM4	5.00	7.60	0.00	GOT 47.5 BBLS OF CEMENT TO SURFACE. ESTIMATED TOP OF TAIL IS AT 568.96 FT.
Event	21	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	5/4/2018	12:00:00	USER				DISCUSSED RIGGING DOWN HAZARDS AND PROCEDURE ACCORDING TO HMS.
Event	22	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	5/4/2018	13:00:00	USER				HELD MEETING WITH ALL HES EMPLOYEES IN CONVOY TO DISCUSS DIRECTIONS AND HAZARDS ASSOCIATED WITH DRIVING, ALL FIT TO DRIVE.
Event	23	Depart Location	Depart Location	5/4/2018	13:30:00	USER				PRE JOURNEY MANAGEMENT PRIOR TO DEPARTURE.

3.0 Attachments

3.1 Hagar 5-64 15-16-1BHZ Surface.png

