

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/31/2018

Submitted Date:

09/04/2018

Document Number:

682403956

FIELD INSPECTION FORM

Loc ID 302901 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All inspections

General Comment:

This is an Interim Reclamation and Stormwater Inspection at the battery location. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Operator has failed to control and manage weeds along the access road and portions of the location. Refer to the attached inspection photos.

Corrective Action: Comply with Rule 603.f .

Date: 09/18/2018

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: [Berm BMP in need of repair. Sediment discharge was observed off location.](#)
[BMPs shall be selected based on site-specific conditions, such as slope, soil type, vegetation cover, and proximity to water bodies, and may include maintaining in-place some or all of the construction BMPs until the Location is abandoned and final reclamation is achieved pursuant to Rule 1004. BMPs shall be installed in accordance with good engineering practices.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 09/18/2018

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Note: Notice of Intent to Abandon has been submitted and IN-PROCESS.	binschusc	09/04/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682403957	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4569478