

## Jacobs 29-1 Corrective Actions



Photo 1. The existing blankets were repaired.



Photo 2. More matting arrived and has been installed.