

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2018

Submitted Date:

09/09/2018

Document Number:

691300495**FIELD INSPECTION FORM**
 Loc ID 429711 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hayes, Brandon	970-378-6389	bshayes@dcpmidstream.com	Environmental Specialist
Leonard, Mike		mike.leonard@state.co.us	
Inspections, Field		cogccinspections@srcenergy.com	All Synergy Inspections
Ansel, Ivan	970-378-6367	iansel@dcpmidstream.com	Operations Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433360	TANK BATTERY	AC	06/27/2010		-	MURDOCK 24-34	AC

General Comment:

Inspected FacilitiesFacility ID: 433360 Type: TANK API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: [Inspection document in response to pipeline strike.](#)

According to DCP and SRC company personnel, an unknown vehicle entered into the Murdock Tank Battery location and struck a 1" needle valve attached to 8" gas sales line owned and operated by DCP midstream. Both SRC and DCP resources have responded to the incident. The line was de-energized and isolated at time of inspection. All wells and equipment on the location were de-energized at the time of the incident.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300496	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573746