

APACHE CANYON 26-08V API# 05-071-07559 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 11, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903037



THE PIPES AND RODS THAT WERE LEFT ON THE WELL PAD WERE REMOVED FROM THE LOCATION. THE LIQUID RING COMPRESSOR WAS MOVED BACK CLOSER TO THE SEPARATOR HOUSE.

APACHE CANYON 26-08V API# 05-071-07559 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 11, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903037



THE LIQUID RING COMPRESSOR WAS MOVED BACK CLOSER TO THE SEPARATOR HOUSE AND THE UNUSED EQUIPMENT REMOVED FROM LOCATION TO ADDRESS THE HOUSEKEEPING ISSUES.

APACHE CANYON 26-08V API# 05-071-07559 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 11, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903037



THE LEASE SIGN WAS REATTACHED TO THE SEPARATOR HOUSE USING LARGER WASHERS FOR A MORE SECURE FIT.