

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401760593

Date Received:

09/12/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 687903041
Inspection Date: 08/22/2018 FIR Submit Date: 08/23/2018 FIR Status:

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308125

Location Name: APACHE CANYON-634S68W Number: 25NESW County: LAS ANIMAS
Qtrqtr: NESW Sec: 25 Twp: 34S Range: 68W Meridian: 6
Latitude: 37.053400 Longitude: -104.950900

FACILITY - API Number: 05-071-00 Facility ID: 262539

Facility Name: APACHE CANYON Number: 25-11V
Qtrqtr: NESW Sec: 25 Twp: 34S Range: 68W Meridian: 6
Latitude: 37.053400 Longitude: -104.950900

CORRECTIVE ACTIONS:

1 CA# 118141

Corrective Action: Complete work on access lease road. Date: 10/08/2018

Response: CA COMPLETED Date of Completion: 09/11/2018

Operator Comment: All of the upgrades to the access road are complete. See attached photo log for details.

COGCC Decision:

COGCC
Representative:

2 CA# 118142

Corrective Action: Complete work on erosion and BMP's on access road and Southern end of well pad.

Date: 10/08/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator Comment: Installed a berm diversion at the entrance to the well pad to direct run on to the existing culvert outlet. Regraded the access road and well pad surface to address the rutting and erosion issues. Installed a berm diversion on the south end of the well pad to direct run off to the undisturbed natural vegetation. See attached photo log for details.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All work for this location is complete. The BMP implementation for the access road and well pad are complete. The erosion issues have been addressed. See attached photo log for details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed:

Title: Sr. Environmental Tech.

Date: 9/12/2018 11:16:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401760620	BMP implementation and erosion issues addressed
-----------	---

Total Attach: 1 Files