

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401758780

Date Received:

09/11/2018

FIR RESOLUTION FORM

CA Summary:

3 of 5 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Amato, Joseph

719-845-2110/719-859-2263

josephamato@tcenergy.us

Oakman, Kari

kari.oakman@state.co.us

Graber, Candice (Nikki)

candice.graber@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 682600545

Inspection Date: 09/07/2018

FIR Submit Date: 09/10/2018

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 309508

Location Name: APACHE CANYON-634S67W Number: 3NESW County: LAS ANIMAS

Qtrqr: NESW Sec: 3 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.111183 Longitude: -104.878807

FACILITY - API Number: 05-071-00 Facility ID: 297294

Facility Name: APACHE CANYON Number: 03-11

Qtrqr: NESW Sec: 3 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.111183 Longitude: -104.878807

CORRECTIVE ACTIONS:

1 ☒ CA# 118541

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 10/10/2018

Response: CA COMPLETED

Date of Completion: 09/10/2018

Operator Comment: The absorbent pads were removed from containment and disposed of in accordance with 907.e. The oil accumulation in the containment was removed by vacuum truck and disposed of in accordance with 907.e. Please see attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: Attached photos document compliance with Corrective Action

3 ☒ CA# 118543

Corrective Action: Absorbent pads are intended to be used to clean up spills not as a spill prevention method. Operator should treat the cause of the leak instead of the symptom. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/11/2018

Response: CA COMPLETED

Date of Completion: 09/10/2018

Operator Comment: The mechanic discovered that the oil leak was coming from the oil filter. A new filter was installed securely to comply with Rule 605.d. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: Attached photos document compliance with Corrective Action

4 ☒ CA# 118544

Corrective Action: Comply with Rule 603.f .

Date: 09/20/2018

Response: CA COMPLETED

Date of Completion: 09/10/2018

Operator Comment: The trash in the production pit was removed to comply with Rule 603.f. Please see attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: Attached photos document compliance with Corrective Action

OPERATOR COMMENT AND SUBMITTAL

Comment: (3) out of (5) Corrective Actions have been addressed, see attached photo log for details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 9/11/2018 8:55:09 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

2100079	Photos
401758780	FIR RESOLUTION SUBMITTED

Total Attach: 2 Files