

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401391167
Date Received:
08/30/2017

FIR RESOLUTION FORM

CA Summary:
1 of 4 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10469
Name of Operator: ENERGY INVESTMENTS INC
Address: PO BOX 17630
City: GOLDEN State: CO Zip: 80402
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Neidel, Kris		kris.neidel@state.co.us
		dnr_cogccenforcement@state.co.us
Fischer, Alex		alex.fischer@state.co.us
		dnr_cogcc_Engineering@state.co.us
Miller, Ann	303-912-2188	ann@energy-investments.com
Leonard, Mike		mike.leonard@state.co.us
Chamberlain, Stephen	303-526-0871	energyinv@msn.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689800143
Inspection Date: 08/07/2017 FIR Submit Date: 08/10/2017 FIR Status:

Inspected Operator Information:

Company Name: ENERGY INVESTMENTS INC Company Number: 10469
Address: PO BOX 17630
City: GOLDEN State: CO Zip: 80402

LOCATION - Location ID: 316782

Location Name: WOLF MOUNTAIN-67N87W Number: 15SWNE County: ROUTT
Qtrqtr: SWNE Sec: 15 Twp: 7N Range: 87W Meridian: 6
Latitude: 40.567424 Longitude: -107.131070

FACILITY - API Number: 05-107-00 Facility ID: 273763

Facility Name: WOLF MOUNTAIN Number: 15-2-7-87
Qtrqtr: SWNE Sec: 15 Twp: 7N Range: 87W Meridian: 6
Latitude: 40.567424 Longitude: -107.131070

CORRECTIVE ACTIONS:

2 CA# 90904

Corrective Action: "Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan."

Date: 08/21/2017

Response: CA COMPLETED

Date of Completion: 08/30/2017

Operator Comment: We have LOTO the flowlines at the Wolf Mountain 15-2. Pictures are attached. No flowlines are located within 1,000 feet of any structure.

COGCC Decision: **Not Approved**

COGCC Representative: Attached photos show risers painted with fluorescent paint, in preparation for abandonment. No evidence of LOTO in photos.

COGCC Supervisor: Photos are not adequate pending re inspection.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ann Miller

Signed: _____

Title: Business Manager

Date: 8/30/2017 2:42:25 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401391167	FIR RESOLUTION SUBMITTED
401391179	Wolf 15-2 Pipe LOTO
401391189	Wolf ROW LOTO
401391191	Wolf Pipe LOTO (1)
401391193	Wolf Pipe LOTO (2)
401391208	Wolf Pipe LOTO (3)
401391213	Wolf Pipe LOTO (4)

Total Attach: 7 Files