

APACHE CANYON 01-14 API# 05-071-07944 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 18, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903055



PHOTO 1: THE ACCESS ROAD TO THE WELL PAD WAS CROWNED TO ESTABLISH SHEET FLOW WHICH ELIMINATED THE TIRE RUTTING.

APACHE CANYON 01-14 API# 05-071-07944 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 18, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903055



PHOTO 2: THE ACCESS ROAD TO THE WELL PAD WAS CROWNED TO ESTABLISH SHEET FLOW WHICH ELIMINATED THE SURFACE EROSION.

APACHE CANYON 01-14 API# 05-071-07944 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 18, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903055



PHOTO 3: THE DAMAGED GALVANIZED CULVERT ON THE MAIN LEASE ROAD WAS REMOVED.

APACHE CANYON 01-14 API# 05-071-07944 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 18, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903055



PHOTO 4: THE DAMAGED CULVERT ON THE MAIN LEASE ROAD WAS REMOVED AND A NEW GALVANIZED CULVERT WAS INSTALLED.

APACHE CANYON 01-14 API# 05-071-07944 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 18, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903055



PHOTO 5: MAIN LEASE ROAD WEST OF THE ACCESS ROAD TO APACHE CANYON 01-14.