

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2018

Submitted Date:

09/26/2018

Document Number:

681701089**FIELD INSPECTION FORM**
 Loc ID 432260 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**☒ THIS IS A FOLLOW UP INSPECTION☐ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|---------------------------------------|---------------------------------|
| Bankert, Wayne | | wbankert@laramie-energy.com | |
| , Laramie | | cogccnotifications@laramie-energy.com | All Inspections |
| Prescott, Lorne | (970) 812-5311 | lprescott@laramie-energy.com | |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Murray, Richard | | g.richard.murray@state.co.us | |
| Spencer, Stan | | stan.spencer@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|-------------------------------|-------------|
| 457384 | SPILL OR RELEASE | AC | | | - | Homer Deep Unit 9-41 PW Spill | EI |
| 457569 | SPILL OR RELEASE | AC | | | - | Homer Deep 9-41 pad PW spill | EI |
| 457570 | SPILL OR RELEASE | AC | | | - | 9-41 Pipe cut at culvert | EI |

General Comment:

COGCC Environmental inspection. Follow-up to Spill/Release IDs #457384, #457569, and #457570. COGCC (A. Fischer and S. Arauza) met with Operator and BLM on location to discuss spill, impacts, and site investigation.

Release of produced water into stormwater ditch and sediment retention pond from damaged 10" poly line was discovered on 9/14/2018 and reported to COGCC via eForm 19 on 9/15/2018 (doc #401764160, Spill ID #457384). Operator discovered that there were two separate impacted areas resulting from produced water releases from two ends of a severed 10" poly line that had been improperly abandoned by previous operator. During discussions between Operator, COGCC, and BLM on inspection date it was decided that operator would report two impacted areas as separate Spill/Release reports (Spill/Release IDs #457569 and #457570) and address impact delineation and remediation for each impacted area separately. See photos.

Inspected FacilitiesFacility ID: 457384 Type: SPILL OR API Number: - Status: AC Insp. Status: EIFacility ID: 457569 Type: SPILL OR API Number: - Status: AC Insp. Status: EIFacility ID: 457570 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spill/Remediation:**

Comment: Based on 9/14/2018 discovery date for Spill/Release IDs #457384, #457569, and #457570, Supplemental eForm 19 Spill Reports are due for all spill IDs. As of 9/26/2018, the operator has only submitted a Supplemental Spill Report for Spill/Release ID #457384.

Corrective Action: Submit eForm 19 Supplemental Spill Report for Spill/Release IDs #457569 and #457570, per Rule 906.b.

Date: 09/26/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------|---|
| 681701096 | 20180919 Field Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4589462 |