



DE	ET	OE	ES
Document Number: 401696243			
Date Received: 07/09/2018			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 76840 Contact Name: Jeff Schneider
 Name of Operator: SCHNEIDER ENERGY SERVICES INC Phone: (970) 867-9437
 Address: P O BOX 889 Fax: (970) 867-9137
 City: FORT MORGAN State: CO Zip: 80701 Email: jeff@schneiderenergy.com
For "Intent" 24 hour notice required, Name: Schure, Kym Tel: (970) 520-3832
COGCC contact: Email: kym.schure@state.co.us

API Number 05-087-08144-00 Well Number: 23-5
 Well Name: VEEMAN
 Location: QtrQtr: NESW Section: 5 Township: 3N Range: 59W Meridian: 6
 County: MORGAN Federal, Indian or State Lease Number: _____
 Field Name: LODESTONE Field Number: 50830

Notice of Intent to Abandon
 Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.252980 Longitude: -104.013030
 GPS Data:
 Date of Measurement: 05/13/2008 PDOP Reading: 1.6 GPS Instrument Operator's Name: DUANE RUSSELL
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	6161	6169			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	322	230	230	0	VISU
1ST	7+7/8	4+1/2	11.6	6,280	200	6,280	5,180	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6110 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 370 ft. with 50 sacks. Leave at least 100 ft. in casing 320 CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Plugging Date: _____
of _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jeff Schneider

Title: President Date: 7/9/2018 Email: Jeff@Schneiderenergy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 10/4/2018

CONDITIONS OF APPROVAL, IF ANY: _____

Expiration Date: 4/3/2019

COA Type	Description
	<p>Bradenhead:</p> <p>1) If there has not been a reported Bradenhead test within 60 days of plugging this well, prior to starting plugging operations a Bradenhead test shall be performed. The Form 17 shall be submitted within 10 days of the test.</p> <p>2) If before opening the Bradenhead valve, the beginning pressure is greater than 25 psi, sampling is required.</p> <p>3) If pressure remains at the conclusion of the test, or if any liquids were present during the test, sampling is required.</p> <p>Sampling shall comply with Operator Guidance - Bradenhead Testing and Reporting Instructions, Appendix A: Liquid and Gas Sampling.</p>
	<p>1) Provide 48 hour notice of MIRU via electronic Form 42.</p> <p>2) Shoe plug: Circulate through perfs to check for acceptable injection rate before setting CICR. If rate/pressure unacceptable do not use CICR. Tag plug 50' above surface casing shoe.</p> <p>3) Surface plug: Cement from 50' to surface in casing and annulus.</p> <p>4) Properly abandon flowlines as per Rule 1105. File electronic Form 42 once abandonment complete. Within 30 days of an operator completing abandonment requirements for an off-location flowline or crude oil transfer line the operator must submit a Flowline Report, Form 44.</p>

Attachment Check List

Att Doc Num	Name
401696243	FORM 6 INTENT SUBMITTED
401696349	WELLBORE DIAGRAM
401696350	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

User Group	Comment	Comment Date
Engineer	Plugging: Submitted form had 10 sks for shoe plug and 10 sks for surface plug. Increased shoe plug to 50 sks, and surface plug to 15 sks.	10/04/2018
Well File Verification	Pass	07/10/2018

Total: 2 comment(s)