

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2018

Submitted Date:

10/04/2018

Document Number:

692600378**FIELD INSPECTION FORM**

Loc ID 335625 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253743	WELL	PR	09/13/2007	GW	125-07621	TUSTIN 41-31	PR

General Comment:[Routine Inspection](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel road through pasture			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign by pumping unit			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Metal panels around unit, wellhead, VGS and meter run			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 2			corrective date
Comment:	Electric panel and telemetry equipment (for Tustin 41-31 well)			
Corrective Action:				Date:
Type: Vertical Separator	# 1			
Comment:	Vertical gas separator 50% buried by meter run (for Tustin 41-31 well)			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Next to wellhead (for Tustin 41-31 well)			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric motor (for Tustin 41-31 well)			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	1 marker broke off (for Tustin 41-31 well)			
Corrective Action:				Date:

Type: Pump Jack	# 1	
Comment:	Weatherford unit (for Tustin 41-31 well)	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:	ECD on north side of tank battery (for Brown SWD)	
Corrective Action:		Date:
Type: Ancillary equipment	# 6	
Comment:	Electric panel by wellhead, telemetry equipment at tank battery, chemical tank by tank battery, 2-electric powered triplex pumps and electric transfer pump in metal shed (for Brown SWD)	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
USED OIL	1	<50 BBLS	CONCRETE SUMP/VAULT		40.016410,-102.438710
Comment:	560gal vault on south side of metal shed (for Brown SWD)				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		40.016410,-102.438710
Comment:	2-300bbl condensate tanks on north side of water tanks (for Brown SWD)				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shared metal containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	253743	Type:	WELL	API Number:	125-07621	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Inventory was copied from Brown SWD and input into this inspection for data purposes only. There are 2 separate inventories, 1 for the Tustin 41-31 and 1 for the Brown SWD. Previous inspection on the Tustin 41-31 was 6/30/15. Brown SWD was inspected 4/23/18	welshb	10/04/2018