

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2018

Submitted Date:

10/04/2018

Document Number:

688400348**FIELD INSPECTION FORM**

Loc ID 319912 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201870	WELL	SI	12/01/2011	GW	001-07274	SIMPSON A 8	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipmet, PU is not connected to well head horses head is gone. No tubing or rods		
Corrective Action:	Comply with Rule 603.f .		Date: 01/01/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Rod Iron		
Corrective Action:			Date:

<b>Equipment:</b>				corrective date
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 201870 Type: WELL API Number: 001-07274 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: PU is not hooked to WH tubing and rods are gone. Well is not plumbed to flow line.  
According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to be TEMPORARILY ABANDON.

Corrective Action: According to rule 707.b. this well is improperly labeled as SHUT IN, this well appears to be TEMPORARILY ABANDON.  
Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3)

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688400349	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599117">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599117</a>