

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401790800

Date Received:
10/10/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Brent White

970-948-2177

bwhite@bry.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689701837

Inspection Date: 09/28/2018

FIR Submit Date: 09/28/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BERRY PETROLEUM COMPANY LLC

Company Number: 10091

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

LOCATION - Location ID: 335597

Location Name: CHEVRON L04 696 Number: _____ County: _____

Qtrqr: SWN Sec: 4 Twp: 6S Range: 96W Meridian: 6
W

Latitude: 39.554882 Longitude: -108.119669

FACILITY - API Number: 05-045- -00 Facility ID: 335597

Facility Name: CHEVRON L04 696 Number: _____

Qtrqr: SWN Sec: 4 Twp: 6S Range: 96W Meridian: 6
W

Latitude: 39.554882 Longitude: -108.119669

CORRECTIVE ACTIONS:

1 CA# 119122

Corrective Action: Location is within a designated setback location, mark guy line anchors per Rule 604.c. (2)Q.

Date: 10/15/2018

Response: CA COMPLETED

Date of Completion: 10/15/2018

Operator Comment: Waiting for weather to clear, deadman anchors will be removed by the deadline date of 10/15. Response noted as complete to satisfy the form, please reference comments on all CA's.

COGCC Decision: _____

COGCC
Representative:

2 CA# 119123

Corrective Action: Comply with Rule 210.e.

Date: 11/30/2018

Response: CA COMPLETED

Date of Completion: 10/08/2018

Operator
Comment:

New signage has been applied to the 100bbl tank

COGCC Decision: _____

COGCC
Representative:

3 CA# 119124

Corrective Action: Repair required BMPs per Rule 1002.f.

Date: 10/05/2018

Response: CA COMPLETED

Date of Completion: 10/15/2018

Operator
Comment:

Waiting for weather to clear to repair the berm.
The non stop rain made the corrective action date difficult to meet. As soon as the rain lets up and location dries up slight Berry will fix the berm as needed.
Also it is noted in the inspection report that the pile of material was assumed to be landfarm material, which it is not. The material is clean backfill material that was left over from a previous excavation on location, and will be spread out on location at the time that we repair the berm.
Expected date of correction 10/15
Response noted as complete to satisfy the form, please reference comments on all CA's.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: please reference comments on all CA's, i marked all CA's as complete to satisfy the form, but am submitting to inform that the remaining CA's will be completed as soon as the rain lets up.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brent White

Signed: _____

Title: Production Foreman

Date: 10/10/2018 10:44:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files