

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401692255

Date Received:

07/25/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Susana Lara-Mesa

303-825-4822

slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 691400548

Inspection Date: 06/15/2018

FIR Submit Date: 06/15/2018

FIR Status: _____

Inspected Operator Information:

Company Name: K P KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 317988

Location Name: MAHONEY-62N67W Number: 20NENE County: WELD

Qtrqr: NENE Sec: 20 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.129740 Longitude: -104.908130

FACILITY - API Number: 05-123-00 Facility ID: 240322

Facility Name: MAHONEY Number: 1

Qtrqr: NENE Sec: 20 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.129740 Longitude: -104.908130

CORRECTIVE ACTIONS:

1 ☒ CA# 116812

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 06/22/2018

Response: CA COMPLETED

Date of Completion: 06/22/2018

Operator
Comment:

Stained soil in separator house has been removed. Please see attached picture.

COGCC Decision: Approved

Based on location photos taken by operator corrective action from DOC#691400548 have been complete.

COGCC Representative: Any corrective actions from previous inspections that have not been address are still applicable.

2 ☒ CA# 116813

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 06/22/2018

Response: CA COMPLETED

Date of Completion: 06/22/2018

Operator Comment: Stained soil around unit has been removed. Please see attached picture.

COGCC Decision: Approved

COGCC Representative: Based on location photos taken by operator corrective action from DOC#691400548 have been complete.
Any corrective actions from previous inspections that have not been address are still applicable.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed:

Title: VP of Engineering

Date: 7/25/2018 3:03:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401692255	FIR RESOLUTION SUBMITTED
401714756	Stained soil removed PIC1
401714760	Stained soil removed PIC2

Total Attach: 3 Files