

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401807573

Date Received:  
10/24/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611

Name of Operator: LONGS PEAK RESOURCES LLC

Address: 2323 S SHEPHERD SUITE 1150

City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Clarkson, David

dclarkson@vrtxep.com

GEISER, EDWARD

(713) 335-4730

egeiser@juncap.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404010

Inspection Date: 09/26/2018

FIR Submit Date: 10/02/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC

Company Number: 10611

Address: 2323 S SHEPHERD SUITE 1150

City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 438066

Location Name: RAILAY Number: 28-3-1CH County: \_\_\_\_\_

Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.985310 Longitude: -104.783590

FACILITY - API Number: 05-123-00 Facility ID: 438066

Facility Name: RAILAY Number: 28-3-1CH

Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.985310 Longitude: -104.783590

CORRECTIVE ACTIONS:

1 CA# 119168

Corrective Action: Comply with Rule 603.f. to control and manage weedy, annual vegetation to prevent weed waste and prevent spread of dispersing seeds onto adjacent lands.

Date: 10/16/2018

Response: CA COMPLETED

Date of Completion: 10/16/2018

Operator Comment: Corrective action to control weeds taken. Will monitor area of re-seed to see where re-seeding will need to be done where no germination on original seeding took place to comply with 603.f.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 119169

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.

Date: 10/30/2018

Response: CA COMPLETED

Date of Completion: 10/16/2018

Operator Comment: Repaired containments around Interim reclamation area to comply with good engineering practice as per Rule 1002.f.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: All necessary corrective actions have been taken.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David Clarkson

Signed: \_\_\_\_\_

Title: COO

Date: 10/24/2018 9:59:17 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

--	--

Total Attach: 0 Files