

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401546462
Date Received:
02/21/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10330
Name of Operator: INVESTMENT EQUIPMENT LLC
Address: 412 W PLATTE AVE
City: FT MORGAN State: CO Zip: 80701
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Jim Chisholm	405-642-9437	investmentequipment@gmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688301157
Inspection Date: 02/08/2018 FIR Submit Date: 02/12/2018 FIR Status: _____

Inspected Operator Information:

Company Name: INVESTMENT EQUIPMENT LLC Company Number: 10330
Address: 412 W PLATTE AVE
City: FT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 317102

Location Name: C H M-63S56W Number: 20SWSW County: WASHINGTON
Qtrqtr: SWS Sec: 20 Twp: 3S Range: 56W Meridian: 6
Latitude: 39.770960 Longitude: -103.683700

FACILITY - API Number: 05-121- -00 Facility ID: 236353

Facility Name: C H M Number: 1-A
Qtrqtr: SWS Sec: 20 Twp: 3S Range: 56W Meridian: 6
Latitude: 39.770960 Longitude: -103.683700

CORRECTIVE ACTIONS:

1 ☒ CA# 114430

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e. Contact area COGCC EPS.

Date: 02/16/2018

Response: CA COMPLETED Date of Completion: 02/14/2018

Operator Comment: 2 gallon bucket of oily dirt removed and replaced with clean dirt.

COGCC Decision: Approved via an AMI

COGCC
Representative:

2 ☒ CA# 114431

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 03/13/2018

Response: CA COMPLETED

Date of Completion: 02/19/2018

Operator
Comment: Brought in dirt to repair rodent holes in berm

COGCC Decision: Approved via an AMI

COGCC
Representative:

3 ☒ CA# 114432

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 03/13/2018

Response: CA COMPLETED

Date of Completion: 02/19/2018

Operator
Comment: Brought in dirt to repair berms

COGCC Decision: Approved via an AMI

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jim Chisholm

Signed: _____

Title: Managing Member

Date: 2/21/2018 4:21:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401546462	FIR RESOLUTION SUBMITTED
401546473	PHOTOS OF WORK DONE
401552343	PHOTOS OF WORK DONE
401552344	PHOTOS OF WORK DONE
401552345	PHOTOS OF WORK DONE

Total Attach: 5 Files