

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401628637

Date Received:

05/03/2018

FIR RESOLUTION FORM

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #210
City: AURORA State: CO Zip: 80016

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Espinosa, Bill		billespinosa30@yahoo.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 677400356
Inspection Date: 01/16/2018 FIR Submit Date: 01/16/2018 FIR Status:

Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC Company Number: 74165
Address: 6155 S MAIN STREET #210
City: AURORA State: CO Zip: 80016

LOCATION - Location ID: 320071

Location Name: CHAMPLIN 485 AMOCO-61S61W Number: 25SESE County:
Qtrqtr: SESE Sec: 25 Twp: 1S Range: 61W Meridian: 6
Latitude: 39.929843 Longitude: -104.152478

FACILITY - API Number: 05-001-00 Facility ID: 320071

Facility Name: CHAMPLIN 485 AMOCO-61S61W Number: 25SESE
Qtrqtr: SESE Sec: 25 Twp: 1S Range: 61W Meridian: 6
Latitude: 39.929843 Longitude: -104.152478

CORRECTIVE ACTIIONS:

1 CA# 113963

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 01/31/2018

Response: CA COMPLETED Date of Completion: 03/05/2018

CA Completed

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 113964

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 01/31/2018

Response: CA COMPLETED

Date of Completion: 03/05/2018

Operator
Comment: CA Completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 113965

Corrective Action: Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.

Date: 01/21/2018

Response: CA COMPLETED

Date of Completion: 03/05/2018

Operator
Comment: CA Completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 CA# 113966

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 01/31/2018

Response: CA COMPLETED

Date of Completion: 03/05/2018

Operator
Comment: CA Completed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

5 CA# 113967

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 02/16/2018

Response: CA COMPLETED

Date of Completion: 03/05/2018

Operator Comment: CA Completed

COGCC Decision: Approved pending re-inspection

COGCC Representative:

6 CA# 113968

Corrective Action: plumb bradenhead to surface

Date: _____

Response: CA COMPLETED

Date of Completion: 03/05/2018

Operator Comment: CA Completed

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA Completed See Photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Bill Espinosa

Signed: _____

Title: Field Supervisor

Date: 5/3/2018 10:55:57 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401628637	FIR RESOLUTION SUBMITTED
401628666	485
401628669	485
401628671	485

Total Attach: 4 Files