

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401430526
Date Received:
10/16/2017

FIR RESOLUTION FORM

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10469
Name of Operator: ENERGY INVESTMENTS INC
Address: PO BOX 17630
City: GOLDEN State: CO Zip: 80402
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|----------------------------|---------------------|-----------------------------------|
| <u>Stephen Chamberlain</u> | <u>303-249-7948</u> | <u>energyinv@msn.com</u> |
| <u>Ann Miller</u> | <u>303-912-2188</u> | <u>ann@energy-investments.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 689800143
Inspection Date: 08/07/2017 FIR Submit Date: 08/10/2017 FIR Status: _____

Inspected Operator Information:

Company Name: ENERGY INVESTMENTS INC Company Number: 10469
Address: PO BOX 17630
City: GOLDEN State: CO Zip: 80402

LOCATION - Location ID: 316782

Location Name: WOLF MOUNTAIN-67N87W Number: 15SWNE County: ROUTT
Qtrqtr: SWNE Sec: 15 Twp: 7N Range: 87W Meridian: 6
Latitude: 40.567424 Longitude: -107.131070

FACILITY - API Number: 05-107- -00 Facility ID: 273763

Facility Name: WOLF MOUNTAIN Number: 15-2-7-87
Qtrqtr: SWNE Sec: 15 Twp: 7N Range: 87W Meridian: 6
Latitude: 40.567424 Longitude: -107.131070

CORRECTIVE ACTIONS:

1 ☒ CA# 90903

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 04/14/2017

Response: CA COMPLETED

Date of Completion: 10/12/2017

Operator Comment: Clean up of the wellhead has been completed. Secondary containment has been accomplished by installing a Trapper F8 Plus around the stuffing box. A third level of containment has been implemented with an overflow barrel set in a plastic berm-like tray. Both are checked daily and spilled oil is recycled as required. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 90906

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 04/14/2017

Response: CA COMPLETED

Date of Completion: 10/12/2017

Operator
Comment:

Secondary containment for lube oils has been installed using a bright yellow SOS Storage Bin at the well head.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ann Miller

Signed: _____

Title: Business Manager

Date: 10/16/2017 11:48:32 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
| 401430526 | FIR RESOLUTION SUBMITTED |
| 401430547 | CA1-Wellhead |
| 401430550 | CA1-Stuffing Box Detail |
| 401430551 | CA1-Stuffing Box |
| 401430552 | CA1-Tertiary Containment |
| 401430554 | CA4-Lube Oil |

Total Attach: 6 Files