

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401823427

Date Received:

11/02/2018

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Zack

Liesenfeld

zack.liesenfeld@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 679300008

Inspection Date: 11/01/2018

FIR Submit Date: 11/01/2018

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqr: SW Sec: 5 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.250444 Longitude: -104.579980

FACILITY - API Number: 05-123-00 Facility ID: 449950

Facility Name: Becker Ranch #2 LA Area Number: 449950

Qtrqr: SW Sec: 5 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.250444 Longitude: -104.579980

CORRECTIVE ACTIONS:

1 ☒ CA# 120101

Corrective Action: Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f. (2)F. Material is tracked onto County or public roads, contact the appropriate authority.

Date: 11/01/2018

Response: CA COMPLETED

Date of Completion: 11/02/2018

Operator Comment: Cattle guard and access tracking pad in place at entrance. However, tracking pad is not adequate and will be improved or additional tracking pad added. No material was observed on county road to the south. Equipment hauling cuttings do not access facility from the south.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 120102

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. See attached photos of areas where material was observed off location. Report in accordance with Rule 906.b.

Date: 11/01/2018

Response: CA COMPLETED

Date of Completion: 11/02/2018

Operator Comment: Material transported off site will be addressed. Reporting in accordance with Rule 906.b. will be conducted if material is thought to be over reporting thresholds.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 120103

Corrective Action: Perform land application in accordance with Rule 907.d.(3)B.

Date: 11/01/2018

Response: CA COMPLETED

Date of Completion: 11/02/2018

Operator Comment: Material will be incorporated in accordance with Rule 907.d.(3)B.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 120104

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 11/01/2018

Response: CA COMPLETED

Date of Completion: 11/02/2018

Operator Comment: BMPs will be repaired in accordance to rule 1002.f.. County road to the west is not directly connected to facility.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Zack Liesenfeld

Signed:

Title: EHS Rep

Date: 11/2/2018 3:17:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401823427	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files