

Shell TR 11-5-697
Api. # 05-045-14093
Inspection # 689702060



Well sign

Shell TR 11-5-697
Api. # 05-045-14093
Inspection # 689702060



Stored equipment and materials not needed for production of well.

Shell TR 11-5-697
Api. # 05-045-14093
Inspection # 689702060



Stored equipment and materials not needed for production of well.

Shell TR 11-5-697
Api. # 05-045-14093
Inspection # 689702060



Stored equipment and materials not needed for production of well.