

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401840237

Date Received:

11/14/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Baca, Matt

matthew.baca@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603182

Inspection Date: 10/05/2018

FIR Submit Date: 10/22/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333123

Location Name: KNIGHT GAS UNIT-N32N7W Number: 17SWNE County: LA PLATA

Qtrqtr: SWNE Sec: 17 Twp: 32N Range: 7W Meridian: N

Latitude: 37.020556 Longitude: -107.628525

FACILITY - API Number: 05-067- -00 Facility ID: 216236

Facility Name: KNIGHT B Number: 1

Qtrqtr: SWNE Sec: 17 Twp: 32N Range: 7W Meridian: N

Latitude: 37.020556 Longitude: -107.628525

CORRECTIVE ACTIONS:

1 CA# 119777

Corrective Action: Remove cable debris.

Date: 11/16/2018

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator
Comment: Actions Complete

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 119778

Corrective Action: Mark or remove guy line anchors.

Date: 11/16/2018

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator
Comment: Actions Complete

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 119780

Corrective Action: Install erosion controls to stabilize erosion within the southern portion of the project area and within the southeastern diversion at the access entrance. Successful revegetation will significantly improve stabilization.

Date: 11/23/2018

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator
Comment: Actions Complete

COGCC Decision: _____

COGCC
Representative: _____

4 CA# 119810

Corrective Action: Revegetate southern cut and fill slopes within the fall or spring seeding windows. Mulching is recommended for successful seedling establishment and soil protection.

Date: 05/01/2019

Response: CA COMPLETED

Date of Completion: 11/07/2018

Operator
Comment: Actions Complete

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Actions Complete

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matthew Baca

Signed: _____

Title: Construction Specialist

Date: 11/14/2018 5:11:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401840240	Corrective Pics

Total Attach: 1 Files