

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/05/2018

Submitted Date:

11/19/2018

Document Number:

688800333**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Hughes, Jim 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Baca, Matthew		matthew.baca@bpx.com	<a href="#">SW Inspection Reports</a>
Deranleau, Greg		greg.deranleau@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458834	SPILL OR RELEASE	AC	11/15/2018		-	Thomas Jacquez E1 PW Line	EI

**General Comment:**

On November 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Thomas Jacquez E #1 PW Line Spill/Release Point ID #458834. For the most recent field inspection report of this facility, please refer to document #690100899. BP representative Steven Moskal and landowner Mrs. Christine Kitts were present during this field inspection.

Inspected Facilities									
Facility ID:	458834	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: [Pleaser refer to Initial Spill/Release Report Document #401825843 for more information regarding this incident.](#)Corrective Action: [The operator shall submit a Supplemental Spill Report no later than ten calendar days after discovery.](#)

Date: 11/14/2018

Reportable: YES

GPS: Lat 37.103723

Long -107.897424

Proximity to Surface Water: 350

Depth to Ground Water: 60

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Spill/Remediation:**Comment: [Per COA on initial Form 19, the operator shall submit a Form 27 Site Investigation and Remediation Workplan.](#)Corrective Action: [Contact COGCC EPS staff regarding Rule 906.c.](#)

Date: 11/21/2018

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>On November 5, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Thomas Jacquez E #1 PW Line Spill/Release Point ID #458834. For the most recent field inspection report of this facility, please refer to document #690100899. BP representative Steven Moskal and landowner Mrs. Christine Kitts were present during this field inspection.</p> <p>On November 4, 2018 the operator left a message reporting a produced water release that entered the Citizen's Animas Ditch near High Flume Canyon on County Road 213. COGCC staff met with Mrs. Kitts and BP representative Steven Moskal on the Kitts' property on November 5, 2018. Absorbent booms had been placed in the ditch, at the inlet to pond #4, and along the High Flume Canyon siphon bypass that runs through the Kitts' property. A noticeable hydrocarbon odor was present.</p> <p>Reportedly a sheen was observed on the upper three ponds near the Kitts' cabin. A sheen was observed in the ditch and Pond #4 during this inspection. Staining and residue was observed along the Citizens Animas ditch, the bypass waterway, and in the ponds. Envirotech was on site installing booms along the impacted area. Booms were used to skim the surface of Pond #4 and absorbent pads were used to soak up gray accumulations near the inlet to the pond.</p> <p>Cottonwood Consulting was reportedly collecting water samples near the confluence of High Flume Canyon and the Animas River. Later that day, Cottonwood staff reported that no visual impacts were observed while collecting samples from High Flume Canyon and immediately downstream of the confluence with the Animas River.</p> <p>Downstream water users had been alerted to the release. BP has staged equipment and personnel on BP Southern Ute 33-10 #24-3 location. BP personnel described the initial and ongoing efforts in dealing with the release. Samples had reportedly been collected near the source where the release entered the ditch. Sample locations included the point of contact on the ditch, ponds #1 and #4 on the Kitts' property, near the High Flume Canyon culvert under CR 213, at the outlet for the High Flume Canyon siphon, as well as near the Rehorn property. Further sampling was discussed with Steven Moskal, including the Kitts' domestic water well and the remaining ponds.</p>	hughesjo	11/19/2018

#### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401845176	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649894">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649894</a>
688800334	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649893">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649893</a>