

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2018

Submitted Date:

11/27/2018

Document Number:

688800357

FIELD INSPECTION FORM

Loc ID 335966 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10091
Name of Operator: BERRY PETROLEUM COMPANY LLC
Address: 5201 TRUXTUN AVENUE #100
City: BAKERSFIELD State: CA Zip: 90339

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Wilbourn, Don		dwilbourn@bry.com	
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent
Arauzo, Steven		steven.arauza@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443338	LAND APPLICATION SITE	AC	09/25/2015		-	Chevron O06 696 443338	EI

General Comment:

On November 7, 2018 COGCC West Environmental Supervisor Alex Fischer, EPS staff Stan Spencer, Steven Arauzo, and Jim Hughes conducted an environmental field inspection of the Berry Chevron O06 696 Land Application Site, Facility ID #443338. For the most recent field inspection report of this facility, please refer to document #688800191.

Location

Lease Road:

Type Access

comment:

Corrective Action:

Date:

Overall Good:

Signs/Marker:

Type OTHER

Comment: Free standing sign near location entrance.

Corrective Action:

Date:

Emergency Contact Number:

Comment: Posted on location sign.

Corrective Action:

Date: _____

Good Housekeeping:

Type DEBRIS

Comment: Continue to remove liner pieces as they become exposed in land farmed material.

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 443338 Type: LAND API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Drill Cuttings	Land Treatment	Adequate		
Comment	Please refer to REM #10050 for more information regarding the land farm project on this location.			
Corrective Action				Date: _____

Spill/Remediation:

Comment:

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Self Inspection	Pass	
				Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On November 7, 2018 COGCC West Environmental Supervisor Alex Fischer, EPS staff Stan Spencer, Steven Arauza, and Jim Hughes conducted an environmental field inspection of the Berry Chevron O06 696 Land Application Site, Facility ID #443338. For the most recent field inspection report of this facility, please refer to document #688800191. Don Wilbourn, Derek Johnson, and Dave Nicholson were on site during this inspection. Continue to remove liner pieces as they become exposed.	hughesjo	11/27/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800358	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4656479