

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401837434
Date Received:
11/13/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Tesla Dougherty	970-304-5245	tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682503927

Inspection Date: 09/20/2018

FIR Submit Date: 09/26/2018

FIR Status:

Inspected Operator Information:

Company Name: PETRO-CANADA RESOURCES (USA) INC

Company Number: 72085

Address: 717 17TH STREET #2900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 394508

Location Name: WESTHOFF, RAY-65N58W Number: 33NENW County:

Qtrqtr: NENW Sec: 33 Twp: 5N Range: 58W Meridian: 6

Latitude: 40.361889 Longitude: -103.873143

FACILITY - API Number: 05-087-00 Facility ID: 394508

Facility Name: WESTHOFF, RAY-65N58W Number: 33NENW

Qtrqtr: NENW Sec: 33 Twp: 5N Range: 58W Meridian: 6

Latitude: 40.361889 Longitude: -103.873143

CORRECTIVE ACTIONS:

1 CA# 119004

Corrective Action: Perform reclamation in accordance to COGCC 1000 series rules and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be complete no later than 11/30/2018.

Date: 11/30/2018

Response: CA COMPLETED Date of Completion: 11/07/2018

The Ray Westhoff # 1 well pad, access road, and adjacent area is native range. The Ray Westhoff # 1 well pad has been returned to original grade. Soils have been deep ripped to a minimum depth of 18-inches; soil

Operator Comment: amendments consisting of elemental sulfur (0.5-ton per acre) have been applied; soils have been agriculturally disked; and the location has been seeded to a native grass seed mix to re-establish native cover and provide soil stability.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 11/13/2018 11:44:26 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401837434	FIR RESOLUTION SUBMITTED
401837441	WESTHOFF RAY 1 (A)
401837444	WESTHOFF RAY 1 (B)

Total Attach: 3 Files