

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401867428

Date Received:

12/10/2018

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

0 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 76840

Name of Operator: SCHNEIDER ENERGY SERVICES INC

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kevin Bothwell

970-867-9437

kbothwell@schneideroilandgas.com

Jeff Schneider

970-867-9437

jeff@schneiderenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404240

Inspection Date: 11/28/2018

FIR Submit Date: 12/04/2018

FIR Status: _____

Inspected Operator Information:

Company Name: SCHNEIDER ENERGY SERVICES INC

Company Number: 76840

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 320521

Location Name: RUBY Number: 1 County: _____

Qtrqr: SWSE Sec: 12 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.973650 Longitude: -104.946970

FACILITY - API Number: 05-001- -00 Facility ID: 320521

Facility Name: RUBY Number: 1

Qtrqr: SWSE Sec: 12 Twp: 1S Range: 68W Meridian: 6

Latitude: 39.973650 Longitude: -104.946970

CORRECTIVE ACTIONS:

1 CA# 120761

Corrective Action: Comply with Rule 1003. Corrective action date is being back dated to when interim reclamation should have been performed.

Date: 03/28/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: Findings are inappropriately tied to multiple wells

Operator Comment: This location was left intact for the other operator (prior to Great Western) to stake and drill wells, which they did and we feel like it should be their responsibility to restore it. The other operator also filed for the variance, not Schneider Oil and Gas

COGCC Decision: _____

COGCC
Representative:

--

2 CA# 120762

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 01/01/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Findings are inappropriately tied to multiple wells

Operator
Comment:

Since this pad was left intact for the other operator (previous to Great Western) to stake and drill wells, which they did, we feel it should be their responsibility to restore and maintain pad.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: It appears that Great Western is moving forward with reclaiming this pad, as we responded to locates from 811 for work described as such

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kevin Bothwell

Signed: _____

Title: Manager

Date: 12/10/2018 12:53:25 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files