

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2018

Submitted Date:

12/11/2018

Document Number:

691200930**FIELD INSPECTION FORM**
 Loc ID 330359 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	All Inspections
Allison, Rick		rick.allison@state.co.us	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251165	WELL	SI	06/01/2016	WA	123-18968	SOONER 21-16-9	SI

General Comment:

This is a **SPILL / RELEASE** inspection.
 Location of spill / release is at Sooner 21-16-9 wellhead.
 (API: 05-123-18968).

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	Informed by field operator of this spill / release. Site appeared to have less than 5 Bbls of what appeared to be water covering an area of approximately 20' x 10' around the wellhead. I did not observe any hydrocarbons that were released. Field operator stated that Foundation Energy regulatory dept. has been advised of the incident. Free fluids appear to have been removed or absorbed by soil. Site appears to have been raked.			
Corrective Action:				Date:

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 251165 Type: WELL API Number: 123-18968 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: SI. Observed well SI. Production records indicate SI since 6/2016.
 Mechanical Integrity Testing (Shut-in Wells)
 No current MIT on record or delinquent as required by Rule 326 (10 Days).
 Form 42 #401820553 indicates 10-day notice of MIT: 11/12/2018.
 Observed no indication of MIT being conducted.

Corrective Action: Date: **COGCC Comments**

Comment	User	Date
COGCC EPS staff has been notified and will follow-up on this incident.	evinsb	12/11/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200932	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4671678