

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/14/2018

Submitted Date:

12/17/2018

Document Number:

682404260

FIELD INSPECTION FORM

Loc ID 449968 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10177
Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION
Address: 950 17TH STREET #2200
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,	720-279-5512	smiller@enerplus.com	All RI/CI inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449968	LOCATION	AC			-	Colorado Lakes Pad	RI

General Comment:

[This is an Interim Reclamation and Stormwater Inspection.](#)

Inspected Facilities

Facility ID: 449968 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IMPROVED PASTURE

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment **Operator has failed to prevent weed establishment on the topsoil stockpile. Note: Appears the Operator attempted to seed the topsoil with desirable vegetation (e.g., blue grama) but weedy, annual vegetation (Kochia) was observed throughout most of the stockpile. Note: For future construction operations, Operator shall consider reducing the slopes of the topsoil stockpile for management purposes and to help protect the topsoil from erosion. Operator has installed temporary erosion controls (i.e., matting) along the slopes of the topsoil.**

Corrective Action **Best management practices to prevent weed establishment shall be implemented. Control and manage weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.**

Date **01/14/2019**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established Fail

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? F

Comment Staff reviewed the well files for the two wells at the pad. This review indicated that the latest date of first production for the wells at the Colorado Lakes Pad was July 13, 2018. During this December 14, 2018, inspection, Staff observed that the northern and eastern area of the pad was not needed for production operations. Despite this, Staff observed that no interim reclamation had been performed on the area not needed for production operations.

Operator shall comply with 1000-Series Rules for Interim Reclamation. All areas not in use for production activities shall be reclaimed in accordance with the 1000-Series Rules within 3 months, on cropland, of the latest production date for the well(s).

Corrective Action If the Operator does not conduct additional operations within 12 months of the spud date (4/21/2018), then comply with CA #1 or CA #2,
CA #1: Perform interim reclamation activities immediately or as soon as practicable.
CA #2: If additional drilling operations have not commenced by 4/21/2019 but future drilling operations are planned, Operator shall submit a Delayed Interim Reclamation variance request.
CA #3: In the event additional operations are to occur before 4/21/2019, Operator shall submit a Rig Schedule showing a scheduled timeline of additional drilling operations via Form 4 Sundry by 12/24/18.

Date 12/14/2018

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IMPROVED PASTURE

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Gully erosion was observed along the main access road road. Note: Silt fence BMP is in need of maintenance along portions of the pad perimeter.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 01/14/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682404261	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4679900